PANT MEMORIAL INSTITUTE - Registered Charity 240435 Pant Memorial Hall, Pant, Oswestry, SY10 9QG



RISK ASSESSMENT - OCTOBER 2025

| What are the hazards? | Who might be harmed and how? | What are you already doing? | Do you need to do anything else to control this risk? | Action by who? | Action by when? |
|-----------------------|---|--|---|----------------------|-----------------|
| Electricity | Users risk electric shocks or burns from faulty insulation Users may bring unsafe equipment to hall Solar equipment and feeds | All work carried out by qualified and registered electricians Five yearly inspection of installation Solar equipment in 'plant room' behind coded door All hall equipment PAT tested annually All plug-in socket covers removed and their future use banned Booking conditions mandate safe equipment – regular hirers offered to join hall PAT session. | Installation test report October 2022 following solar equipment installation – revised February 2023. Revised test Sep 2025 with new panel. Next PAT due November 2025 | Secretary | Ongoing |
| Work at height | Anyone risks injury when working at height. Mobile phone coverage at hall can be poor, so lone users cannot rely on a mobile as a safety aid. | Contractors and hirers reminded that mobile coverage is poor (O2 and Vodafone only, no EE or 3) Hall stepladder not to be used when alone and its condition monitored. Committee members reminded to tell someone that they are at the hall. Any work at height done with min two people present. | No further action needed. | Secretary | Ongoing |
| Hot water | Hot water presents a scald risk. Kitchen has a boiling water device. | 'No children in kitchen' policy with notice placed. 'caution – hot water' stickers in kitchen Boiling water device is secured to wall and positioned for safe use of teapots. Hirer information advises boiling water device in kitchen. Burn dressings included in first aid kit | | Booking secretary | Ongoing |
| Vehicle Movement | Risk of collision or injury from moving vehicles in car park | Car park is small. Good visibility in both directions – bus shelter positioned to avoid blocking view. Remind hirers of need to supervise children at all times due to passing traffic. | Trim plant by car park entrance as needed to ensure clear visibility. | Committee | Ongoing |

| Accidents | Anyone | First aid kits available with BSE approved contents. | | Secretary | Ongoing |
|---------------|--|--|-------------------------------------|-----------|----------|
| Accidents | Anyone | Blue plasters (food preparation) and eye wash bottles | | Secretary | Origoing |
| | | added to standard list. | | | |
| | | First aid kits checked monthly, logged, items replaced | | | |
| | | as needed (or when out of date) | | | |
| | | , | | | |
| Outside Black | Diels of cliening Describe wiels in ins | Accident form system implemented. | And nonlarge and sets and force | Committee | Ongaina |
| Outside Play | Risk of slipping. Possible risk in icy | Area fenced off with gate that is very difficult to open | Any replacement gate and fence | Committee | Ongoing |
| area | weather despite non-slip surface. | from outside and child-proofed from inside. | to be 'no climb' (vertical slats) | | |
| | Children can climb on to brick wall | | with secure fixing. | | |
| | which has drop to tarmac on far | Access door to this area from hall is locked, with key | | | |
| | side. | left on adjacent high window sill. | | | |
| | | Hirers reminded to supervise children at all times. | | | |
| Fire | Risk of injury or death in case of fire | Professional fire risk assessment done November | Continue to monitor stored items | Secretary | Ongoing |
| | | 2017 and all actions implemented. Maximum | and keep to minimum. | | |
| | Building is a single-storey structure | occupancy 120, hirers are advised 100. | | | |
| | with fire exits and ramps at both | Fire sensor installed in plant room July 2023 following | | | |
| | ends. Kitchen fire doors replaced in | internal rearrangement and advice from Chubb. | | | |
| | 2021. | Fire alarm and up to date emergency lighting installed. | | | |
| | | Fire equipment checks in place and logged (rota for | | | |
| | | weekly/monthly check, Chubb for 6/12 month checks) | | | |
| | | No smoking/vaping signs in place. | | | |
| | | No external bins, hirers to remove all rubbish. | | | |
| | | Total ban on gas appliances. Professional caterers | | | |
| | | may use small food-warming burners at their risk and | | | |
| | | responsibility if alarm is set off. | | | |
| | | Regular review of stored items. | | | |
| Hygiene | Food poisoning. Infection spread | Self-employed cleaner visiting as required | Monitor overall cleanliness. | Committee | Ongoing |
| | risk. Vermin attracted by food. | Bin liners provided to help users remove their own | Increase cleaner visits if needed. | | |
| | | rubbish. Blue plasters added to first aid kit. | Check fridge weekly to ensure no | | |
| | | Food storage limited to tea/biscuits in sealed | food left in it (as part of general | | |
| | | containers. | test procedure) | | |
| | | Manual flush installed for urinals (with sign) | | | |
| | | Steam cleaning of floors carried out as required. | | | |
| Manual | Risk of injury if lifting items that are | table rack and trolleys provided. | Update storage room layout | Secretary | Ongoing |
| Handling | too heavy. All chairs and tables are | Room layout and storage information provided. | guidance as required. | | |
| | placed in hall and then returned to | Tables numbered to aid fault reporting. | | | |
| | store after each event. | Signs placed for correct storage. | | | |
| | | | | | |

| Replacing Light Tubes/ cleaning light fittings | All at ceiling level with risk of falling while replacing | Long-life LED panels fitted to main room July 2020 Kitchen/entrance hall ceiling height ensures that fitting cleaning/replacement can be done only by professional with own ladder. Occasional clean of ceiling light shades in toilets needed, as not sealed. | Anyone cleaning lights to ensure have help at hand, take care when using stepladder. Turn off breaker to toilet lights before removing shades. | Committee | Ongoing |
|---|--|--|--|---|---------|
| Children on Premises | Hall is on busy main road and has several separate areas so children can go out of sight. General safeguarding. | Need to supervise children is stressed. "No children in kitchen" sign placed. Safeguarding policy in place. Hiring agreement mandates childcare provisions and DBS checks for commercial hirers running activities for children. Message reinforced to all (including contractors and villagers) that hall access is only by arrangement – no 'just popping in as it was open.' | No further action needed beyond reminders to hirers. | Booking secretary | Ongoing |
| Bouncy Castles | Risk of injury (and damage) from use of these. Insurers mandate only professional suppliers. | Bouncy castles are only allowed inside the hall, limited to 2.4 metre height (i.e. 6 years and under). Hirers must provide copy of public liability to booking secretary before booking is confirmed. | Continue to remind users of this requirement. No hall hire for bouncy castle use unless public liability policy provided. | Booking secretary | Ongoing |
| Violence and Aggression | Risk of escalation of arguments regarding use of hall or car park. Risk to committee member property if they are known to be absent from home. | Personal details of committee members are not public domain. The contact details for the hall are its own address, the booking mobile and generic email addresses. No alcohol licence for hall – any hirers wishing to sell alcohol must obtain their own licence. Committee reminded NOT to give out personal details of other members. (mandated in data protection policy) | | Secretary Committee members | Ongoing |
| Legionnaire's Disease | Risk of infection from legionella bacteria. Risk temperature range for water is 20-45 degrees centigrade. Hot water for kitchen sink and toilets now all from main tank | Legionella prevention mode running in tank. Water heated twice weekly throughout year. No showers 'Boiling' water device for hot drinks is set to 96 degrees | Drain and refill boiling water device if not used for more than a week. If hall is not in regular use, taps to be run and toilets flushed weekly. | Booking secretary to advise secretary if hall out of use. | Ongoing |
| Hazardous Substances | Risk of inhalation or burn injury from cleaning products. | Cleaner provides her own cleaning materials and rubber gloves. No cleaning tasks require materials beyond normal domestic use. Any COSHH substances used by professionals only. | No further action needed | | |

| Storage | Incorrect storage risks injury from | New table storage system and storeroom layout | Continue monitoring of storage. | Secretary | Ongoing |
|----------------|--------------------------------------|--|---------------------------------|-----------|---------|
| | falling objects | implemented September 2019 | Ensure unused items removed. | | |
| | | | Revise storeroom layout as | | |
| | | explanatory signs in place, pictorial where possible. | furniture changes. | | |
| | | Cleaning cupboard fitted with hooks and shelves. | | | |
| Asbestos | Very low risk to users and committee | Asbestos survey carried out January 2018. Some | Review asbestos management | Secretary | Ongoing |
| | members in normal circumstances. | sources identified and recorded. | plan when further works done, | | |
| | Risk to maintenance workers. | 500kg of asbestos removed and professionally | issue to contractors. (plan | | |
| | | disposed during hallway works August 2018. | updated Oct 2022) | | |
| | | Asbestos management plan issued | | | |
| Off site risks | Risks when distributing leaflets for | We cannot control off site hazards, so can only be | No further action possible. | Committee | |
| | events; dog threat, falls, trips | aware. Caution when approaching properties where | | | |
| | | dog heard/seen – if in doubt, avoid. Extra care at | | | |
| | | weekends when dogs are loose. Do not leaflet in icy | | | |
| | | conditions. Look out for loose steps etc. | | | |
| SARS COV-2 | All mandatory precautions ended – | All windows can be opened, keys provided | Continue to monitor government | | |
| (Covid 19) | virus still very prevalent. | throughout building | guidance, if any. | | |
| | Responsibility with hirers but venue | Sign on entrance board reminds attendees of | | | |
| | continues to offer mitigation | the risk and to respect each other | | | |
| | measures. | 'no bin zone' maintained | | | |
| | | hand soap provided (sanitiser does not | | | |
| | | control disease) | | | |
| | | keysafe system allows reduced contact for | | | |
| | | booking secretary | | | |

DATE OF NEXT REVIEW: October 2026